

9 FEB 1960

Received from Chief Ship Surveyor.....

SHIP'S NAME "QUEENWORTH" REPORT Nwc. No. 116762

GB

Standing Conditions of Class: SUBJECT to wavy bottom shell plates B.6 & 7, C.7, 8 & 9 etc. (s.s. from aft) also to set up bottom shell plates (p & s.f.) being specially examined and dealt with by the next Special Survey.

S.R.L. Appendix. (As before ~~of 1959~~)

Surveys due: SPECIAL SURVEY (C) due 10,59. Postponement until some time before expiration of the year of grace approved 11.9.59.

Location of Present Survey: (~~Afloat and in~~ dry dock)

Docking: General Examination: Wear and tear repairs: Damage (cause not stated) involving shell plates E.4 & F.5 (s.s.), E.8 & F.10 (p.s.) from forward.

Special Features:

Interim Certificate in order (Yes-~~No~~)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

Work to be completed by: See Committee Minute.

Recommendation:


SUBMITTED record of 'DS 12,59' be assigned, SUBJECT to wavy bottom shell plates B.6 & 7, C.7, 8 & 9 etc. (s.s. from aft), set up bottom shell plates (p & s.f) also to indented side shell plates E.4 & F.5 (s.s.) and E.8 & F.10 (p.s.) from forward all being specially examined and dealt with as necessary by the Special Survey, but further ACTION be DEFERRED for Special Survey.

DS 12,59. Subject Amended.

IN S.R.L. APPENDIX.
Stern plates (p & s) indented.
Shell plates A 3 & 4 (p.s.a) and keel plates Nos. 2 & 3 wavy.

Handwritten initials and date: bsl, 2/2/60

IT IS FURTHER SUBMITTED postponement of Special Survey until 10,60 merits approval.



Blk(new)

Date