

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICE

Date of writing Report April 21st 1958 When handed in at Local Office..... 19..... Port of MONTREAL

No. in Reg. Book 25141 Survey held at Prescott, Ont. Date, First Survey 25th March Last Survey April 16th 1958
 (No. of Visits TWO)

25141 on the Steel "QUEENSTON"

TONNAGE:— Built at Sunderland By whom Swan, Hunter & Wigham Richdson. When 1927 5
 GROSS 1976 Owners Colonial Steamships Limited.
 UNDER DK..... Managers R. Scott Misener. Port belonging to Toronto
 NET 1136

Surveyed Afloat or in Dry Dock? Afloat Name of Dock..... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 11959 Port MTL

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS*	MBS* 5,54
Great Lakes and Limited Gulf of St. Lawrence service 12,54	MBS 2,57 TS(CL) 12,54N
Lake S.S. 12,54	SPS 2,57
A.S. 4,57	

	ITEMS EXAMINED AND CONDITION FOUND, ETC.
Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	- do -
Between decks.	- do -
Deck & deck erections.	- do -
Machinery Space.	- do -
Under Engines & Boilers.	- do -
Masts, Rigging & Outfit.	- do -
Windlass & Hawse Pipes.	- do -
Air & Sounding Pipes with closing appliances.	- do -
Pumps and Pumping arrangements outside machinery space.	- do -
Steering arrangements including gear.	- do -
W.T. Doors & Sluice valves.	- do -
Ventilator coamings with their closing appliances.	- do -
Hatchway coamings with their closing appliances.	- do -
Casings, companionways and their closing appliances.	- do -
Superstructure bulkheads with their closing appliances.	- do -
Guard rails & freeing ports.	- do -
Overboard discharges, also ash chutes & other shell openings.	- do -

	EXAMINED	TESTED	CONDITION
Peaks	Yes		Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams (Tankers)			
Pump Rooms			
Has a Load Line Annual Renewal Survey been held?	No.	C.G. Load Line.	
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No.		

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4.54" or "to remain as classed and to have record of docking, 1.54 and the notation Lake S.S. 4.54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,58


Survey Fee \$ 66.00
 Special Damage or Repair Fee (if any) USSA \$ 4.00
 Travelling Expenses \$ 25.00
 Second Surveyor's Fee (if any) \$
 Committee's Minute

Fees applied for, MAY 1 1958

THURSDAY 22 MAY 1958

Character Assigned AS 4.58
MBS 2.58

W. Heatlie
 Surveyor to Lloyd's Register of Shipping.
 (Wm. HEATLIE)



© 2021 Lloyd's Register of Shipping.

Lloyd's Register Foundation

003742-003749-0059

-0061

Noted for Header

If so, is the Report sent now, or when will it be sent?

If the Surveyors are requested not to write on or below the space for LOA

Is a Certificate