

COPY

DESTROY
1975

Ship's name KINGSTON DIAMOND

Port

No

Class is subject to - NIL

Next survey date 19-12-64

Docking

Wear down 2.5%

Damage stated due to wire rope fouling propeller. All tips of propeller blades buckled and scored, all bolts in stern bush flange broken now renewed. The Surveyor recommends the propeller be specially examined and dealt with as necessary on vessel's arrival at Plymouth.

It is submitted that this vessel is eligible to remain as **CLASSED**.

Subject as recommended



© 2021

Lloyd's Register
Foundation