

27 JAN 1965

Ship's Name SS/~~MS~~ " KINGSTON DIAMOND "

Gross tons 581 Port of Registry Fleetwood . Port Reykjavik

Date of build 11.39 Is there a Rpt. 9? Yes Rpt. No. 4 3 5 4 .

No. of visits 3 First date 19.12.64 Last date 19.12.64

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) LIV 164 041

Date of completing rpt. 20.1.65 Surveyed at, if different from Port above

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. 4.64

Has a Load Line Survey been held? No Summer freeboard as verified

State which additional Rpt. 8 is attached: (Cont); (PS); ~~(DR)~~; ~~(EQ)~~; ~~(Rig)~~

Survey fees Kr. ~~1500.00~~ 600.00 Damage fee Expenses

S.A. fee

29 JAN 1965

I have surveyed the above-named ship in accordance with the Rules for D S (propeller damage)

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with/without fresh record of dry docking D S 12.64 .

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee FRIDAY 12 FEB 1965

Minute D.S. 12.64 Subject

Write byjn check.

Viggo R. Lenn. Surveyor to Lloyd's Register of Shipping



© 2021

Lloyd's Register Foundation

ALSO FOR
SPL FOR
TRO
SRL
POSTING
HEADER
CERT

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS * KINGSTON DIAMOND *

S.S. () Due

Port Reykjavik

Rpt. No. 4 3 5 4 .

5

<u>Examined & condition</u>		<u>Examined & condition</u>	
In dry dock from	19.12.64	* Air & sounding pipes	above deck - Good
„ „ „ to	19.12.64	Doublers under „ „	N.E.
Shell plating	Good	Steering arrangements (main)	Good
Sternframe	Good	„ „ (aux)	Good
Rudder	Good	Windlass	Good
Was rudder lifted?	No	Masts & rigging	
Plating, etc. in way of shell openings	None	Hand pumps & suction	
Side scuttles & deadlights	None	W.T. doors	
Overbd. scuppers & discharges	N.E.	Bulwarks, freeing ports, etc.	
F.P. spaces	N.E.	Summer freeboard as verified	
Chain locker	N.E.		
A.P. spaces	N.E.		
Engine space	N.E.		
Boiler space	N.E.		
Under E. & B.	N.E.		
Coal bunker	None		
Tunnel & well	N.E.		
Cement, asphalt, etc., on btm. shell	N.E.		
Weather decks	Good		
* Casings	Good		
* Deckhouses	Good		
* Superstructures	Good		
* Skylights	Good		
* Companionways	Good		
* Hatchways	Good		
* Ventilators	Good		
Other items:			

EQUIPMENT:

Equipment letter	
Fee ltr., if diff. from eqpt. ltr.	
Anchor: No. on board	
Cables {	State if ranged No
	Length on board
	Mean dias. range from to
	Rule length Dia.
Mooring ropes	

* These items to include their closing appliances
 Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

