

EXTRACT FROM ROTTERDAM CLASSING LETTER.

23rd December, 1952.

MARTHA VINKE". Before submitting your Report No.35469 to the Committee, I shall be glad if you will state the number and size of the safety valves fitted to the forward boiler and confirm that the super-heaters originally fitted to the replace boiler when built were not retained when the boiler was re-installed.

It is also concluded that the reference in the report to "a second 4 Furnaces boiler" is intended to read "a second hand 4 furnaces boiler" and that the after boiler of the vessel is that which was originally fitted but confirmation on these points is also desired.

The identification marks of the original boiler were according to the records in this Office:-

BC Test
No. 6178
TP. 387lb.
WP. 225lb.
H.W.
23.4.41.

BC Test
6179
TP. 387lb.
WP. 225lb.
H.W.
30.4.41.

Notations of LMC*MS 10,52 and BS 6,52 will be the information requested has been furnished.

© 2021

Lloyd's Register
Foundation