

30th April, 1957.

HAMBURG

5463, 75, 82, 83, 90, 95, 99 - As recommended.

RMC.5511, 12 -- As recommended.

5506 "TAYBANK" As recommended, except that in accordance with the provisions of the third paragraph of Circular No. 2089 a record of DBS 3,57 has been assigned.

5503 "PHEMIUS" As recommended. I shall be glad if you will state whether the new electrical cables fitted to the new 175 KW generator are vulcanised rubber insulated or impregnated paper/varnished cambric-insulated as this will materially affect the permissible current.



© 2020

Lloyd's Register  
Foundation

003750-003762-0078