

Received from Chief Ship Surveyor

L 2 MAY 1961

SHIPS NAME

"NAVICELLA"

REPORT

Rot.

No. 51278

GB

Outstanding Conditions of Class: SUBJECT to indented shell plates H.5 & 6, J.6 (p.s.a) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (~~As before~~ or None)

Nature of Present Survey: (~~As before~~ and in dry dock)

Docking: Damage - cause not stated.

Recommendation:

SUBMITTED record of 'DS 3,61' be assigned as recommended, subject as above, and to indented shell plate E.8 (p.s.f) being examined and dealt with as necessary before the ship is re-commissioned.

DS 3,61 Subject


NOTE:-

The Surveyors point out it is Owners' intention to lay the ship up in a British port. See also Shell Tankers letter dated 6.4.61.

Blk (new)

003750-003762-0096

present.



© 2020

Lloyd's Register
Foundation

W.S. 11
26.4.61