

100A1 (Classification Contemplated).  
"Examined 8.47"

of Surveyors

Received from Chief Surveyors

S NAME

"IVYBANK"

Report

LIV.

125724

No.

22225

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

PERIODICAL ~~NO.~~ SPECIAL SURVEY/PARTLY HELD. Repairs.

For Classification.

When proposed to be completed

of Survey held, &amp;c. - See report.

NOTED

Subject to permanent repairs to indented shell plating (p & s) at the first convenient opportunity, and to buckled bulkhead between Nos. 1 & 2 holds and to 45 fathoms of chain cable being supplied at the first opportunity.

© 2020

Lloyd's Register  
Foundation

CLASSIFICATION  
SURVEY PARTLY HELD.

003750-003762-0197

Briage, Angle,