

s.s. "SAMYORK"

It is submitted the Sydney Surveyors be informed by air mail that the new Owners, Messrs. Andrew Weir & Co., have arranged that this vessel is to be classed with Lloyd's Register and they have requested that the Surveyors at Sydney get in touch with their Marine Superintendent, who will advise them exactly when and where the vessel will be available for examination.

Action should be taken in this case as required for "Liberty" ships, as set forth in the Circular Letter dated 23rd May, 1946. The Surveyors should also verify that the precautionary measures detailed in the attached copy of Circular Letter No. 101 issued by the Admiralty in January, 1944, have been given effect to. Copies of the plans of standard "Liberty" ships should be forwarded for the Surveyors' information and they should be informed that, while certain modifications may have been made to the arrangements to suit particular Yards, the information given on these plans should be of assistance to the Surveyors in preparing the First Entry Report.

The following information has been supplied by the Owners:-

Vessel delivered	October 29th, 1943.
Annual Loadline Survey due	October, 1947.
Boiler Survey due	January, 1948.
Tail Shaft Survey due	November, 1949.
6 months out of dry dock	May, 1st, 1947.
Tail shaft drawn at last survey.	



© 2020

16th June, 1947.

Lloyd's Register
Foundation

003750-003762-0215