

23 DEC 1958

Received from Chief Ship Surveyor.....

SHIP'S NAME "NORTHWOOD" REPORT Nwc. No. 115741.
AR.

standing Conditions of Class: Subject to leaky rivets in bilge plating in way of No. 3 hold (s.s) being permanently repaired next drydocking and ~~to permanent repairs~~ to shell plating (temporarily repaired) in No. 3 hold (s.s) being permanently repaired at the next drydocking.

Postponement of Certificate ~~(As before)~~ or None)

Surveys due: SPECIAL SURVEY (C) becomes due 12,58. Proposal to postpone the Survey until 12,59 approved, subject to satisfactory General Examination in drydock (see letter 4.9.58).

Location of Present Survey: ~~(At sea)~~ and in dry dock)

Docking; General Examination, as above; damage repairs, including conditions of class; deferred repairs to shell plating (pitting);

Special Features: The Surveyors recommended deferrment of the S.S. until 12,59.

Interim Certificate in order (Yes-~~No~~-None)

Items Outstanding: (If any for S.S.) All.

NONE

to be completed by:

Recommendation: SUBMITTED record of 'DS 11,58' be assigned as recommended SUBJECT to pitted shell plates in 'D' & 'E' strakes (p & s) abreast Nos. 1, 2 & 3 holds being specially examined and dealt with as necessary ~~next~~ S.S., but without other condition.
AT THE

DS 11,58. Subject.
Without.

IT IS FURTHER SUBMITTED the proposal to postpone the S.S. until 12,59 merits the favourable consideration of the Committee.



© 2020
Lloyd's Register
Foundation