




Lloyd's Register of Shipping,

95, Bothwell Street, GLASGOW, C.2.

Report enclosed.




S. Dear Sir,

I am duly in receipt of your letter of the 17th instant regarding Glasgow First Entry Report No. 69178 on the S.S. "EMPIRE KUMASI", and in reply to your enquiry regarding the dynamo test sheets the Surveyors state that due to an alteration in the design of the vessel - to carry general cargo instead of refrigerated cargo - the size of the generators was reduced, and the only suitable machines available were supplied by the Admiralty.

The test certificates were not received from the D.D.M.B. until the installation was complete, so that the Surveyors were not aware until a very late date that the requirements of the Rules in respect of high voltage tests had not been complied with.

I may say that there is another vessel of the same type being built in this district at present, and I shall be glad to learn what action should be taken regarding the high voltage tests on similar generators, which are also being supplied by/



Lloyd's Register
Foundation
P.T.O.

005788-003799-0160

Insert/in S.R.L:- (A power anchor and 45 fathoms of chain

by the Admiralty.

The particulars for boiler and superheater omitted from the report have been inserted and it is returned herewith.

I am, Dear Sir,

Yours faithfully,

R. Mullis

Secretary to the Glasgow Committee.

The Secretary,
WOKINGHAM.

W
R

25 JAN 1945

Shaw



© 2020

Lloyd's Register Foundation