

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No: 24305
31st October, 1963.

R
JMC/CB

Dear Sirs,

s.s. "JALAKWTU"

With reference to the classification in the Society's Register Book, I would inform you that the Main Boiler Survey became due at the end of July, and I shall be glad to learn what arrangements are proposed to be made for this inspection to be held.

I take this opportunity to remind you that the Special Survey will become due at the end of February, 1964, and the hull class of this vessel is at present subject to the set in shell plate G.7 etc. (port side from aft) masts and rigging, leaky sounding pipes to Nos.3 and 5 D.B. tanks (starboard side) (cement box) (Nos.5 D.B. tanks not be used as such until permanently repaired) leaky air pipe in No.2 'tween decks (port side) (cement box) and indented and corrugated shell plating (port and starboard) being specially examined and dealt with as necessary by the end of February, 1964.

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Scindia Steamships (London) Ltd.,
Kempson House,
Camomile Street,
LONDON, E.C.3.



© 2020

Lloyd's Register
Foundation

003800-003807-0131