

COPY

EA

Ship's name "MULBERRY HILL"Port

GIB

No.

4949

Last survey date 20.9.64.Class is subject to

For conditions of class see previous endorsement.  
 ACTION is DEFERRED for a short time for equipment.

S.R.L. Appendix (as before or none)Nature of present survey (afloat and in drydock)

Equipment - bower anchor and 60 fms. of chain cable as  
 above supplied but not verified.

Recommendation SUBJECT to a bower anchor and 60 fms. of chain cable  
 (supplied Gib.9.64) being verified with certificates  
 at the earliest opportunity.

As Now Subject  
 amended.

IN S.R.L. APPENDIX

Lower stem bar set over to port.  
 Bottom shell plating slightly corrugated.  
 Shell plates A.5 and B.1 (p.s.a) A.4 (p.s.f)  
 and stern wrapper plate indented.  
 F.9, E.9 & 10 (s.s.amids) slightly wavy.  
 Shell plates G.5 and H.5 (p.s.f) indented and wavy.

IT IS FURTHER SUBMITTED the Surveyors be requested to  
 forward a Report 8 (Eq).

End. S.I

© 2020

Lloyd's Register  
 Foundation

ENGR. SURS. TO NOTE.