

003808-003815-0158

COPY

EA
Ship's name "MULBERRY HILL"

Port IST No. 5550

Last survey date 7.8.64.

Class is subject to

For conditions of class see previous endorsement.

ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Docking: Examination and repairs on account of contact
and grounding including subject items.

Equipment - examination of subject item.

Recommendation

SUBMITTED record of DS 7,64 be assigned, subject to
one bower anchor and 60 fathoms of chain cable being
supplied at the earliest opportunity, without
other conditions, but ACTION be DEFERRED for a
short time for Equipment.

DS 7,64 Subject
without.

DELETE FROM S.R.L.

Drydocking (grounding).

S.R.L. APPENDIX (AMENDED)

Lower stem bar set over to port.

Bottom shell plating slightly corrugated.


Shell plates A.5 and B.1 (p.s.a) A.4 (p.s.f)

and stern wrapper plate indented.

F.9, E.9 & 10 (s.s. amids) slightly wavy.

Shell plates G.5 and H.5 (p.s.f) indented & wavy.

End. S.1



© 2020

Lloyd's Register
Foundation