

COPY

Ship's name *MULBERRY HILL*

Port

*MSL*

No. *13863*

Class is subject to -

Last survey date *3-3-64*

*the propeller, aft end of stern bush and all outside fastenings being specially examined and dealt with as necessary at the next dry-docking*

*It was stated the ship had grounded on muddy bottom. It was reported no apparent damage to propeller and the Surveyor recommended the propeller and fastenings be specially examined at the next dry docking by 6/64. It is submitted the subject be as above.*

**It is submitted that this vessel is eligible to remain as CLASSED.**

*Subject as above*

*LD*

*6/64*



© 2020

Lloyd's Register  
Foundation