

14 JUN 1963

Ship's Name SS/MS "MULBERRY HILL" Gross tons 7121

Is there a rpt. 8? Yes Port Calcutta Rpt. No. 342

No. of visits 1 First date and Last date 2/6/63

Interim Cert. issued & copy herewith? No Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)

Date of completing rpt. 6/6/63 Surveyed at, if different from Port above

Is a rpt. 9A attached? No MN 505 Nature of survey Docking

Survey fees Docking Rs. 140/- Damage fee - Expenses -

S.A. fee -

DOCKING

Propeller good Sea connections good Oil gland -

Fastenings good Wear down of stern bush 3/16"

Has screw/tube shaft been drawn? no Date of examn. -

Has shaft been changed? no Has shaft now fitted been previously used? -

Has shaft now examined/fitted a continuous liner? - Approved oil gland? -

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves { Sat
adjusted to { Spt

Boiler securing arrangements

Main economisers Exhaust gas heated economisers

Steam heated steam generators Steam generator safety valves adjusted to

Forced circulating pumps Funnel

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules? Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed W/A without fresh record of survey.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

WEDNESDAY 17 JUNE 1963
As now

Hugh Cameron
HUGH CAMERON.
Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

003808-003815-0191

Lloyd's Register
Foundation