

S.S. "EMPIRE GRACE"

Extract from Liverpool Rpt.9 No.117696 dated 17.4.42.
Received 6.5.42.

As regards the cooling fan motors for the Refrigerating Installation, it was reported on arrival at Liverpool that bad commutation had developed after prolonged running.

The motor Manufacturer's representative attended, when it was found that unsuitable brushes were fitted. Carbon brushes of correct grade have now been fitted, and the motors tested under all conditions, and found, so far as could be seen, to be satisfactory.

It is recommended that these motors be examined and tested on the vessel's return from present voyage.

RECOMMENDATION

..... and to all the cooling fan motors of the Refrigerating Installation being examined and tested under full working conditions on the vessel's return from her present voyage.



© 2020

Lloyd's Register Foundation

003816-003823-0081

Brine Circulating pumps, closed.
Brine Cooling System, closed or open *closed.*

1-14" x 1/2" V.D. ram - - - electrically
Are the pipes and tanks galvanised on the inside