

Ship's name

^{u/v} "WAIRANGI"

Port

Rollerton (SA)

23 JUL 1963

No. 56281

Class is subject to Main high & C.S. pump Last survey date 22/5/63
all-inlet valves being removed at next D.I.

Repairs.

Starb. M.E. No. 1 unit damaged due to failure of exhaust piston tie-rod stated due to uneven landing of tie-rod nut on yoke and some parts of the unit renewed by spares. The Surveyor recommends that the starboard main engine No. 1 lower exhaust-piston yoke be replaced or machined in way of tie-rod nut-landings by ~~7/63~~ 7/63 (2 months limit).

C.S. Advanced.

It is submitted that this vessel is eligible to remain as CLASSED, subject

as above and as now renewed.

Wey.
23/7/63

Lloyd's Register
Foundation