

COPY

Ship's name

WAIRANGI

Port

Rollerton (M)

No. 56281

Class is subject to

Main high Y C.S. pump

Last survey date

29/7/63

ex-inlet valves being removed at next D.D.

### Repairs.

Starb. M.E. No. 4 mild damaged due to failure of exhaust piston tie-rod stated due to uneven landing of tie-rod nut on yoke in some parts of the unit removed by spacers. The Surveyor recommends that the Starboard main engine No. 1 lower exhaust-piston yoke be replaced or machined in way of tie-rod nut-landing by ~~7/63~~ 7/63 (2 months limit).

### C.S. Advanced.

It is submitted that this vessel is eligible to remain as **CLASSED**, subject to above and

© 2020



Lloyd's Register  
Foundation