

"MUSHTARI"


Refer Postponed Survey's memo dated 7.2.58 with reference to comments on testing of chain cables.

The case is submitted for consideration, and in this connection it is recommended that the Figure '1' in the ship's class be deleted and a dash (-) inserted in lieu until the 195 fathoms of chain cable are tested as now recommended.

It would appear from reports here that all the chain cable on board is of Rule length and diameter and not deficient in quality.

IT IS ALSO SUBMITTED the Surveyor be requested to furnish, as soon as possible, the present minimum mean diameter of each length of chain cable on board and confirm that from his examination the chain cable is all in good condition.

would agree but as this
meanwhile not in
accordance with the Rules
Shew to Sir Guy Repner, &
therefore withdraw from today's Committee


7.2.58.

R.M.F.
11/2/58



© 2020

Lloyd's Register
Foundation

003816-003823-0232