

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C.3
18th December, 1953.

Classm(S)
CPA

Dear Sirs,

Motorships "SRI TUTOH"
"SRI TINJAR"

Further to my letter of the 21st October last, I have to acquaint you that in addition to the verification of the equipment, propellers complying with the Rules require to be fitted in each case before assignment of class.

The Hong Kong Surveyors state that new propellers have, in fact, been forwarded from their port, but it is not known if they have been fitted. The Owners' Representative has promised to investigate the matter on his return to Borneo, but in the meantime, I shall be glad if you will inform Lloyd's Agents at Labuan with a view to their Surveyor being instructed to verify the fitting of propellers complying with the Rules.

Yours faithfully,

Assistant Clerk to the
Classification Committee

The Surveyors,
SINGAPORE.



© 2020

Lloyd's Register
Foundation

003824-003831-0042