

m.s. "SRI TINJAR"

Before this case receives final consideration IT IS SUBMITTED the SINGAPORE Surveyors be requested to ascertain from the Surveyor to Lloyd's Agents at LABUAN if the anchors and cables forwarded from Hong Kong have been placed on board and to verify the equipment with the certificate numbers as follows:-

Bower Anchors Y7411 and Y 7412

Stream Anchor Y4717

Stud Link Chain Cable Y4733

Stream Chain Y4736

ld

15.10.53.



© 2020

Lloyd's Register
Foundation

003824-003831-0046