

LLOYD'S REGISTER OF SHIPPING



Port _____ of Narvik,

15th December, 1959.

This is to Certify that I have

part
Surveyed the Machinery of the steel motor ship "Panaghia" 4494 tons gross of Puerto Limon, whilst lying afloat at Tromsø on the 3rd December, 1959 and subsequently on account of damage to the aft auxiliary generator engine, port side, stated occurred on the 27th November, 1959 whilst on voyage Arkangelsk - Salonica, Greece, and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the ~~following~~ Survey Records be ^{retained} ~~XXXX~~ in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book, subject to Aft auxiliary generator engine, port side, being used only as stand by engine and repaired and completely overhauled on arrival Greece from present voyage, and also subject to other conditions at present attached to the machinery's class being dealt with as previously recommended.

arts now examined:
(C.S. Items only)

P. Berg Rolness,
2nd Surveyor.

Engineer Surveyor to Lloyd's Register
Alf Jacobsen.

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be noted that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or in any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

150m,3,59 (MADE AND PRINTED IN ENGLAND.)

003824-003831-0082