

4 MAR 1938

by Chief Ship Surveyor

Received from Chief Ship Surveyor

L'S NAME "RAPANA" Rpt. Rot. No. 26535

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to the sternframe, E.W. repair and reinforced 5,36, being specially examined at the next drydocking.

The Rotterdam Surveyors report the vessel placed in dry dock, bottom cleaned and coated.

A new bower anchor has been supplied.

It is submitted the vessel appears worthy to remain as classed with record of survey 2,38, subject as above.

100A1 )  
2,38 Rot. ) Subject etc.  
Carrying petroleum in bulk.

The Surveyors should be informed it is concluded the E.W. repairs to sternframe, as above, have been specially examined and found efficient, but the ~~Surveyors~~ should state if this is so.

2020  
W

Lloyd's Register  
Foundation