

CR

12th June, 1957.

Dear Sirs,

S.S. "MAHOUT"

The above vessel has been under survey at this Port for repairs to the starboard after boiler inboard high combustion chamber back plate in which a pin-hole had developed due to corrosion at the radius and as a temporary repair a pad has been welded in way of the wasted area.

The back plates of the other combustion chambers of this boiler were found to be corroded in the same area and it is recommended that they be examined and dealt with before the end of 6.57. The Owner's superintendent states that the boiler survey will be carried out at Glasgow to which Port is due to arrive about 21st inst. Kindly give the case your usual close attention.

Yours faithfully,

THE SURVEYORS.

Per. *W. Allan*

The Surveyors,
Glasgow.



© 2020

Lloyd's Register
Foundation

003832-003837-0023