

Received from Chief Ship Surveyor.....

117 NOV 1961

SHIP'S NAME "MAI RICKMERS" REPORT Ham. No. 10958

GB

Outstanding Conditions of Class:

SUBJECT to fractured shell plate in 1st strake above bilge (frames 89-90) in way of the starboard oil fuel bunker being dealt with as necessary at a European port on completion of the present voyage and to 'tween deck plating in way of poop accommodation (s.s.) being examined and dealt with as necessary at the next drydocking.

R.L. Appendix. (~~As before~~ None)

Structure of Present Survey: (~~As before~~ in dry dock)

Docking: Examination of conditions of class:
Minor wear and tear repairs.

Recommendation:

SUBMITTED record of 'DS 10,61' be assigned as recommended, subject to fractured shell plate in 1st strake above bilge frames 89/90 in way of oil fuel bunker (s.s.) and to 'tween deck plating in way of poop accommodation (s.s.) being examined and dealt with as necessary on the ship's arrival at Japan.

DS 10,61 Subject
Amended.

NOTE:- It appears this ship is proceeding to Japan for breaking up.



© 2020

Lloyd's Register
Foundation

W.S. 1 7/1/61