

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

IMA

REPORT

Rot.

No. 32542

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to forward keel plate and A.1 (s.s.) at the next Special Survey, with endorsement of class.

The ROTTERDAM Surveyors report (7.50) ship examined in dry dock, bottom coated and, on account of damage due to contact with dock fenders, a few shell plates (p & s) dealt with, including G.4 (s.s.) and G.6 (p.s.), as above.

Keel plate No. 1 and shell plate A.1, as above, also dealt with.

IT IS SUBMITTED this ship is worthy to remain asclassified with record of docking 7.50, without either condition or endorsement of class.

7.50 Rot. Without.

DELETE Endorsement of Class 'B'.

22  
8  
50



© 2020

Lloyd's Register  
Foundation

003832-003837-0111