

COPY OF CLASSING LETTER

23rd February, 1954.

MALMO

3304. As recommended.

3302 "SVITHIOD". As recommended except that the vessel's machinery class has been continued subject to repairs to main engine No. 6 after back column and to port auxiliary engine No. 2 cylinder block being further examined before the end of July, 1954. In this connection I would point out that repairs by the Metalock process and welded repairs to main engine columns are not usually considered as permanent without a further examination after a period of service.



© 2020

Lloyd's Register  
Foundation

003832-003837-0231