

COPY

LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE.

14th December, 1959.

Part

This is to Certify that I have

Surveyed the Machinery of the m.v. "SUNETTA" 7,965 tons gross
of THE HAGUE whilst the vessel lay afloat and was in drydock
at the Port of Singapore on the 19th November, 1959 & subsequently
on account of Docking, ABS and CS of Engines.
and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book
ABS 12/59 now and CS (with date) when the survey has been completed
and that her Machinery Classification Record be continued in the Book.

Part now examined: Propeller. Aft end of stern bush. Underwater
(C. Items only) fastenings. Auxiliary boiler.

Main Engine Nos. 1, 2, 6 & 7 cylinders, covers, pistons and rods,
valves and gears.
No. 7 connecting rod, top ends and guide.
No. 6 & 7 crankpins and bearings.
No. 3 and 4 journals and bearings.
Attached Piston Cooling Water pump.

Auxiliaries Stand-by Piston cooling water pump. Aft feed pump.
Stand-by circulating pump and engine.
General Service pump.

W. Ward
Engineer Surveyor to Lloyd's Register
over
(W. WARD.)

KEY TO ABBREVIATIONS

BS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
S	Continuous Survey of Engines	SPS	Steampipe Survey
BS	Donkey Boiler Survey	TS	Tailshaft Survey
IS	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
IS	Main Boiler Survey	TSN	Tailshaft renewed
S	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report, certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

(Cert. B.1.) 150m,3,5 MADE AND PRINTED IN ENGLAND.)

003838-003845-0032

