

LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE.

14th December, 1959.

This is to Certify that I have

Part

Surveyed the Machinery of the M.V. "SUNETTA" 7965 tons gross of THE HAGUE whilst the vessel lay afloat and was in drydock at the Port of Singapore on the 24th November, 1959, and subsequently on account of Auxiliary Boiler Survey,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

ABS 12/59 now

and that her Machinery Classification Record be continued in the Book.

Parts now examined:

(C.S. Items only)

Auxiliary Boiler examined throughout together with safety valves, mountings, manhole doors and fastenings and all found, or now placed, in good order. Subsequently, boiler examined under steam and safety valves adjusted to required pressure.

Compression Ring Thicknesses Forward $\frac{3}{16}$ " Aft $\frac{9}{32}$ "

Engineer Surveyor to Lloyd's Register
(W. WARD).

KEY TO ABBREVIATIONS

| | | | |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey | SGS | Steam Generator Survey |
| CS | Continuous Survey of Engines | SPS | Steampipe Survey |
| DBS | Donkey Boiler Survey | TS | Tailshaft Survey |
| ES | Engine Special Survey | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey | TSN | Tailshaft renewed |
| MES | Modified Survey of Oil Engines | TS(OG) | Tailshaft Survey—Oil Gland |
| OF | Fitted for oil fuel (date) FP above 150°F. | | |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1.) 15th, 3, 59 (MADE AND PRINTED IN ENGLAND.)

© 2021

Lloyd's Register
Foundation

003838-003845-0033