

Received from Chief Ship Surveyor

11.4 APR 1959

NAME "WAVE PREMIER" REPORT Sng. No. 13143.
AR.

Working Conditions of Class: Subject to fractured shell plate in way of upper stringer frame 66 (p.s) being specially examined and dealt with as necessary next drydocking.

Content of Certificate (As before ~~on None~~)

of Present Survey: (Afloat ~~and in dry dock~~)

W & T repairs;

Recommendation: SUBJECT as above;

As now. Subject.

IN S.R.L. APPENDIX.

Shell plate No.4 from fwd. in 3rd below sheer (p.s) indented.

C.S.S. Records Dept.
to note.



© 2020

Lloyd's Register
Foundation

003846-003857-0191