

4E

27 APR 1956

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "CALDARE".....

REPORT.....

Syd. No. 28887

Repairs to Engines on account of propeller striking a submerged
object.

Vessel examined afloat, but the Surveyors recommend port propeller be specially examined at the next dry docking.

IT IS SUBMITTED the vessel is eligible to remain AS CLASSED, subject as now recommended.

The Surveyors should be told it is usual for port of Survey to be entered alongside the report No., and for special conditions of class to be included under "Opinion of Machinery and Recommendations."



© 2020

[Handwritten signature]

Lloyd's Register
Foundation

24.4.56.

003867-005874-00911