

T. S. S. Pophocles.

Bel: 8672.

During construction it was noticed that the left wing combustion chamber side plate of one of the single ended boilers was laminated. The defect was cut out; and in the Secretary's letter E of 27th Sept. 1921 approval was given for the plate to be left in its present condition subject to examination on the vessel's return from her first voyage.

It is submitted that
this vessel is eligible for
THE RECORD.

† L. M. C. - 2.22. CL.

4 steam turbines geared to 2 screw shafts
1334 N.H.P.


subject to the defective side plate of the left wing combustion chamber of one of the single ended boilers being specially examined on the vessel's return from her first voyage.

It is concluded that the screw shafts are fitted with continuous liners, but this should be confirmed.

For 21/2/22

GRH

*L.G.
16/2/22.*



© 2020

Lloyd's Register
Foundation

003867-003874-0166