

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 3551 (6 Lines)

6th August, 1954.

Dear Sirs,

Motorship "ORESTES"

Further to my letter of the 9th April last a report of a survey which was carried out in May last has been received from the Society's Surveyors at Singapore, from which it is noted that repairs were carried out to damage stated to have been sustained as a result of fire in No. 2 'tween deck at Sydney in March last.

It was reported that a bower anchor had been lost and it was recommended that a bower anchor be supplied at the earliest opportunity. The Committee have continued the class subject to this matter receiving attention. I shall be glad to learn what arrangements you propose making in this respect.

The class of this ship is now subject as above and to permanent repairs to indented shell plates in 'K' and 'L' strakes etc., starboard side, being carried out by the end of next month.

I take this opportunity to point out that a Donkey Boiler Survey will become due at the end of this month.

Yours faithfully,

c.c. Liv.

Clerk to the
Classification Committee.
Messrs. Alfred Holt & Co.,
India Buildings,
Water Street,
LIVERPOOL, 2.



© 2020

Lloyd's Register
Foundation

003875-003883-0024