

SHIP'S NAME "OFESTES" REPORT Sng. No. 10254

Outstanding Conditions of Class: Subject to permanent repairs to indented shell plates in 'K' & 'L' strakes, etc. (s.s.) by 9,54, also to buckled upper deck plating, etc. at forward end of centre castle being examined and dealt with as necessary by next drydocking (fire dam.).

Endorsement of Class (B) (~~As before~~ None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Damage repairs (fire) to the upper deck plating, etc. as above: Alterations in accordance with approved plan: Equipment (a bower anchor reported lost).

Recommendation: SUBJECT to permanent repairs to indented shell plates in 'K' & 'L' strakes, etc. (s.s.) by 9,54, and to a bower anchor being supplied at the earliest opportunity, but without other conditions.

As Now. Subject Without.

~~IN S.R.L.~~
Extended S.S.



SPK
© 2020 *2020-64*

Lloyd's Register Foundation

003875-003883-0025