

"ORESTES" Sing. 8774 & 8775

For previous history of this case see endorsement  
10.10.51.

In view of Singapore Surveyors' letter of 9.11.51.  
IT IS SUBMITTED action as regards classification be deferred  
for drilling of the bottom shell amidships, and the further  
examination (and action as considered necessary) of shell  
plates F.2 (p & s) (below renewal thickness) and No.6 & 7  
D.B. tank top plating (insulation to lift as necessary).

*dlb*  
15th November, 1951



© 2020

Lloyd's Register  
Foundation

003875-003883-0034