

the Surveyor examine the drain plugs of the Main Boilers? *Yes*, and of the Donkey Boilers? *Yes*

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor (13) 0 MAY 1951

US NAME *Stina*

2 REPORTS L.A. No. 289.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.

This Survey, due *10.50* ~~partly~~ ^{now} held ~~_____~~ ^{now}

~~completed, and the following repairs carried out (due to _____):~~

Screw shaft examined.

It is submitted the vessel is eligible to remain as classed, with notation of *MBS * 11.50* as recommended.

*Bl.S. 11.50
S. 8.50*

003884-003894-0018



© 2020

Lloyd's Register Foundation

tted at
at a cor
50.
ear, cal
ll top
e spu
d up
sitt
Steir
exam
L & W
Stew
Main