

14 FEB 1957

Received from Chief Ship Surveyor

SHIP'S NAME "FALCON" REPORT Lon. No. 134988
GB

Outstanding Conditions of Class:

Subject to rudder, sternframe and steering gear being specially examined for possible damage (collision) next drydocking, and to indented counter plate (s.s.a.) and shell connection to ash shoot being permanently repaired, also to one mooring wire being renewed, by the Special Survey.

ACTION is DEFERRED for Special Survey by 3,57.

Endorsement of Class (B) (As before ~~on None~~)

Surveys due: SPECIAL SURVEY (C) due 1,56. Postponement until 3,57 approved 26.10.56.

Nature of Present Survey: (Afloat ~~and in dry dock~~)

General Examination afloat as required by letter dated 22.10.56.

Special Features:

Is Interim Certificate in order (Yes ~~No None~~)

Items Outstanding: (~~If any~~ for S.S. ~~or A.S.~~)

ALL ITEMS.

S.S. to be completed by:

Recommendation:

SUBMITTED ACTION be DEFERRED for Special Survey by 3,57, subject as above, with Endorsement (B).

As Now. Subject.

ENDORSEMENT OF CLASS (B).
Indented sheerstrake plate
and bulwark plate (p.s.f.).

Postponement of Special Survey until 3,57 already approved.



© 2020
31.1.51

Lloyd's Register
Foundation

003884-003894-0050