

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

P. O. Box 106, Las Palmas,
Grand Canary, Canary Islands

Telegrams: Carbonera, Las Palmas

Telephone Nos. Office { 1771
2466
House 6581

15/2/57.

RECEIVED

28 MAR 1957

Ans'd

24th March 1957.


Dear Sir,

m.v. 'BRUNA'

I have been advised, after considerable waiting that the above vessel has had her arrangements, changed, and that she sailed from Lanzarote (one of the local islands) for Liberia without making her promised call at Las Palmas. It has not therefore been possible to verify the anchors as promised and I wrote to the vessel on this matter some time ago and await the reply. I have also been in touch with the Owner in Tenerife, and he has promised that the matter will have his attention soon.

I have no drawing meantime available of the screw shaft arrangement, and I have been unsuccessfully endeavouring to get one from the slipway, but I would say that it was of the "Newark Gland" type, and I shall forward a drawing at the earliest opportunity.

Yours faithfully,


J. Stuart Jolly

The Secretary
Lloyd's Register of Shipping
LONDON



© 2020

Lloyd's Register
Foundation

003884-003894-0135

SPER

CLASSIFICATION

K

AM

[Handwritten signature]

R.A.P.

Await further information

adll
29-3-57

1101 1101 1101

1101 1101 1101

[Faint, mostly illegible typed text, possibly bleed-through from the reverse side of the page]

1101 1101 1101

1101 1101 1101

© 2020



Lloyd's Register Foundation

LOYD'S REGISTER OF SHIPPING

Box 100, Gas Buildings

Double Yarns Cable