


"BRUNA"

If Owners request Reclassification
IT IS SUBMITTED the Surveyor be advised that
it is concluded that:-

1. full requirements of a SPECIAL SURVEY(C) have been complied with,
2. no major repairs have been effected to the structure since the ship was disclassified,
3. no structural arrangements have been carried out since the class lapsed.
4. also that full particulars of the equipment on board, including weights and tests of anchors, and length, diameter and tests of chain cable should be furnished for approval.


A complete Machinery Survey has been
conducted
The main shaft renewed
an additional bilge pump
fitted


8.10.56.

in extinguishing arrangements

accordance with Notice N° 2019 (Tr)

The Owners should be advised that the torsional
characteristics of the main propelling machinery
have not been submitted for consideration and the
Machinery Certificate will be endorsed accordingly


9-10-56



© 2020

Lloyd's Register
Foundation

003884-003894-0153