

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

lassn(S)  
RNC

71, Fenchurch Street, E.C.3

1st October, 1953.

Dear Sirs,

Motorship "BRUNA"

I have your letter of the 3rd September, and am obliged to you for forwarding a copy of the report of survey issued last February by the Comisariado Espanol Maritimo at Ceuta.

It is noted therefrom that a repair was carried out on the screwshaft by filling in the wasted parts by means of electric welding, and in this connection it is thought well to inform you that a repair of this nature is not approved by this Society, such repairs being unreliable, resulting sometimes in failure without warning.

It is therefore considered that a new screwshaft should be fitted at the first opportunity, and I shall be obliged if you will kindly furnish me, for the information of the Committee, with your proposals as to what arrangements you are able to make for this matter to be dealt with at an early date.


I would add that the vessel's class is also subject to an additional bilge pump being fitted at the first available opportunity.

Yours faithfully,

c.c. Gib.

Assistant Clerk to  
the Classification Committee.

Messrs. Societe Liberienne de Transports  
Maritimes S.A.,  
Rue Don Fernando de Portugal 44, 2° D  
TANGIER, Morocco.



© 2020

Lloyd's Register  
Foundation

003884-003894-0188