

"BRUNA"

IT IS SUBMITTED the Gibraltar Surveyor be informed of the Owners statement regarding the re-examination of the crewshaft and be requested to state whether the repairs were effected under survey.

JH *Em*

11.8.53.

Ande Gub:
Rs.



© 2020

Lloyd's Register
Foundation

003884-003894-0193