

5c.8.11.

Received by Chief Ship Surveyor

13/3/2

N/W TEMPLE CROSS

Received from Chief Ship Surveyor

F.E.

VESSEL'S NAME

At &amp; Eng Central No. 2 Rpt. Inc No. 61924

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

32.5

Depth "d"

10.34

Framing: Table No.

3 page 9

Description

Ordinary (single angle)

Longitudinal No.

2990

Proportions

Length =

8.0

Depth =

Deck Sheerstrake

25 in less of .30



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100A1 (class) for tonning purposes, as recommended.

$\pm$  100A1 (class) for tonning purposes  
18% (etc)



H.B. APT 124

BK 6" H.B.H. Gun Lloyd at 60

© 2020

Lloyd's Register Foundation

003895-003905-0085

Angles on upper edge

Spacing

Deck Material &amp; thickness

Poop Deck Stringer Plate, breadth &amp; thickness