

4



LLOYD'S REGISTER OF SHIPPING,

810 HENNEN BUILDING,

NEW ORLEANS, LA.,

J. M. BUCHANAN,
AND ENGINEER SURVEYOR.LLOYD'S REGISTER OF SHIPPING
NEW YORK
Oct: 30th. 1918.

REC'D NOV 2- 1918

ANS'D _____

The Secretary,

New York,

Dear Sir,

"MEXOIL"

I am in receipt of your letter of the 21st: inst: regarding this new Steamer, and in reply, the rudder head or stock is 6 1/2" diam:, the stiffening of collision and longitudinal bulkheads is in accordance with the approved plans, and as required, the single angle connecting girder to bottom transverses is 5" x 5", and the sheerstrake is increased in thickness at the break of poop, the thickness being 13/16"; The only tie plates on poop deck are in way of deck houses, and are 9" x 5/16", besides the deck stringer plate; The pillars in forehold, one pillar under after end of hatch coaming, two channels back to back 10"x3 1/2" x 9/16"; In similar cases I shall include these particulars in my Report.

I am,

Yours faithfully



© 2020

Lloyd's Register
Foundation

003895-003905-0165

M
22.11.18

YOUNG INTERPRETER

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

"LLOYD'S"

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18

1. 11. 18



© 2020
Lloyd's Register
Foundation