

EX Greenland w/w TRUMAN X

F.E.

Received by Surveyor 12.12.05 EX

Received from Chief Ship Surveyor

VESSEL'S Ste. Steam Trawler "Concord"

Rpt. Hull No. 17404

The of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points entered in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	10 1/16" in lieu of 8 1/2"	Not required.
Star Sheerstrake . .		

Description of Framing:— Ordinary, 5 1/16" in lieu of 5 1/2" thick, and (viz., ordinary, deep, zed, channel or bulb-angle). Spaced 1" closer than required.

This vessel appears to have been built in accordance with the and the approved plans, and it is submitted she is eligible to be ed + 100 A 1 ("Steel") Steam Trawler as recommended.

+ 100 A 1 ("Steel") Steam Trawler

18R.

BK 7 1/2" 4BH Cam. Lloyd's A & CP Q 64' F 19'



C. Hop
© 2022

Lloyd's Register
Foundation

003906-003413-0108

Plate or Tee Buid
Angles on Upper Edge
Spacing

40 40

Angle on ditto
Tie Plates