

Ship's name "GEMMA" Port SNG No. 17307.

Last survey date 10/4/64.

Class is subject to:-

M.B.

- (1) Port and Starboard Sterntube Nuts being specially examined and dealt with by the next dry docking.
- (2) Port and Starboard LP Cylinders (Metalocked 2/63) being specially examined by 2/64 (12 months limit).

MBS due 2.64. Now held.

CSM advanced.

Docking. Wear-down: P & S - 3/32".

SRL: Item No. (2) - Cylinders specially examined and found in good condition and it is considered they should be re-examined by 4/65.

Item No. (1) - Cement removed from port and starboard sterntube nuts and they were found to remain efficient but the Surveyor recommends they be re-examined at the next dry docking.

IT IS SUBMITTED that this vessel is eligible for the record MBS 4/64 now, subject as above as now amended.


14.5.64.

NOTE.

Metalock repairs to the LP cylinders were carried out in 2/63 and not 2/62 as stated in the SRL and the Surveyor should be informed that the subject has been extended to 4/65 and be requested to issue an amended Interim Certificate.