

Blandy Brothers Shipping & Agency, S. A.

Coal Depot Proprietors
SHIP AGENTS, LLOYD'S AGENTS.
CORRESPONDENTS.
BLANDY BROTHERS & Co. Ltd.
3. LONDON WALL BUILDINGS,
LONDON, E. C. 2
BLANDY BROTHERS & Co. Ltd.
FUNCHAL, MADEIRA.

TENERIFFE BRANCH
MARINA, 45
SANTA CRUZ

Telegraphic Addresses:-
BLANDY-LAS PALMAS
BLANDY-TENERIFE

Codes:
BENTLEY'S, 2nd PHRASE CODE.
A. B. C. 5th
SCOTTS, 10th

Las Palmas de Gran Canaria,

APARTADO, 12/106

16th November, 1963

JFM/am

The Secretary
Lloyds Register of Shipping
71, Fenchurch Street,
London E.C.3.

Dear Sir,

s.s. "CLAN MACAULAY", British
L.P. Port Engine defective -
Repairs carried out Las Palmas
16th/19th August, 1963.

We would advise that we received notification from the local S.S. agents on the 16th August that the Master of the above vessel had radioed advising that LP Port Engine was defective, vessel was proceeding on starboard engine only, and requested the attendance of Lloyds Surveyor.

Upon the arrival of the "CLAN MACAULAY" at midnight of the 16th August, we proceed aboard accompanied by Mr. Santiago Armas. Survey was carried out, recommendations made for necessary repairs which were immediately put in hand. Port Engine compound completed on the morning of the 19th August after which two hour sea trial was carried out to Surveyor's satisfaction and vessel sailed for Dakar at 1800 hours of the 19th August 1963.

We enclose herewith Original of Survey Report and remain, dear Sirs,

Yours faithfully,
BLANDY BROTHERS SHIPPING & AGENCY, S.A.,



© 2020

Lloyd's Register
Foundation

003958-003963-0127