

COPY FOR RPTS. 8 & 9 (ORIG. RMC)

BRITISH & COMMONWEALTH (GROUP MANAGEMENT) LIMITED

DIRECTORS:
SIR NICHOLAS CAYZER, BT. (CHAIRMAN)
THE RT. HON. LORD ROTHERWICK
BERNARD G. S. CAYZER
HON. ANTHONY CAYZER
JAMES A. THOMSON

CAYZER HOUSE
2 & 4 ST. MARY AXE
LONDON, E.C. 3

TELEGRAMS: CAYZER, LONDON, TELEX
CABLES: CAYZER, LONDON, E.C.3
TELEX No.: 22628

TELEPHONE
AVENUE 4343 EXT. No.

OUR REF. TECHNICAL/AH/2018

YOUR REF.

12th November, 1963. 18/4

Lloyd's Register of Shipping,
71 Fenchurch Street,
London, E.C.3.

Dear Sirs,

"CLAN MACAULAY"

We thank you for your letter dated 6th instant from which we note that while the above vessel was at Takoradi repairs were effected to the port cooling water pump engine following damage to the eccentric rod. (RMC)

It is observed that the Surveyor recommends that this rod should be examined and dealt with on completion of the present voyage and before the end of next month. In this connection, we wish to advise you that at the moment the future of this vessel is uncertain but should it be decided to keep the vessel in service we will get in touch with you again at a later date regarding this matter.

Yours faithfully,
For THE CLAN LINE STEAMERS LIMITED

Hamison

CT

SUPT. ENGINEER

Agents for: Cayzer, Irvine & Company, Limited. The Clan Line Steamers Limited. The Union-Castle Mail Steamship Company, Limited. Houston Line Limited.
King Line Limited. The Scottish Shire Line Limited. The Scottish Tanker Company, Limited. Neptune Shipping Company, Limited. Turnbull Martin & Company Limited.
London & Southampton Stevedoring Company, Limited. The Caledonia Stevedoring Company, Limited. British & Commonwealth (Property Management) Limited.
The Tendimus Society Limited.



© 2020

Lloyd's Register

TAH 22-10

003958-003963-0144