

EA

9 MAR 1965

Ship's name "NAN AN"

Port

CAL

No.

1550

Last survey date

12.2.65

Class is subject to

NONE

S.R.L. Appendix (as before ~~or XXXXXXXX~~)

Nature of present survey (afloat ~~and in drydock~~)

Damage - contact, involving side shell plating  
etc. (s.s.f) - temporary repairs.

Recommendation

SUBJECT to damaged stem and stem plating and  
No.4 plate in 3rd strake below sheer etc.  
(p.s.from fwd) being specially examined and  
dealt with as necessary next drydocking.

As Now Subject.

IN S.R.L.APPENDIX

Shell plates E.2, F.4 & 5 (s.s.from fwd) and  
K.6 in way of No.5 hold (p.s) indented.

© 2021

Lloyd's Register  
Foundation