

Owners Cia. Panamena Marittima,

Owner's address (If not already in R.B.)

Managers San Gerassimo S.A.

Port of Registry PANAMA

ACTION is DEFERRED for drydocking(grounding).

Surveyors

Received from Chief Surveyors

IME

"MARCELLA"

REPORT

Bal.

No.

11362

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Survey

Equipment: Docking:

~~When dock~~

Damage repairs.

NOTED.

Subject to 75 fathoms of chain cable being renewed by 4,58.

DELETE FROM S.R.L.

Drydocking(grounding).

IN L.O.E.

(Pitted keel plating to be kept under observation).



© 2021

Lloyd's Register
Foundation

003971-003979-0006